Oil Field Environmental Incident Summary

Responsible Party: OXY USA INC. **Well Operator:** OXY USA INC.

Well Name: EMIL VEVERKA 4-17-20H-143-95

Field Name: MURPHY CREEK Well File #: 26746

Date Incident:4/22/2015Time Incident:16:00Facility ID Number:County:DUNNTwp:143Rng:95Sec:17Qtr:

Location Description:

Submitted By: Robyn Espinoza Received By:

Contact Person: Robyn Espinoza

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.2 MileDistance Nearest Water Well:0.2 Mile

Type of Incident: Fire

Release Contained in Dike: Yes - On Constructed Well Site
Spilled Units Recovered Units Followup Units
Oil
Brine
Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/23/2015 Clean Up Concluded: 4/22/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

A root cause investigation is underway, any necessary repairs will be made to ensure this does not happen again.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 4/23/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.